

SDMS Document ID



2118901

2118901

EPA NO. U590002

FILE NO. P2-13

**PROCESS FLOWCHART
AND
PORCESS DESCRIPTION**

Attachment L

Information Request #6

6. PRODUCTION PLAN

6.1 Flowsheet and Process Description

The target end-product for the first year of operation will be cobalt sulfate solution containing 8 % cobalt.

The production of cobalt sulfate solution involves two key steps: dissolution of cobalt in sulfuric acid followed by purification by removing impurity metals. This last step is not necessary if virgin metal is used.

If a crystal product is desired at a later date, the additional steps of crystallization, drying and packaging will also be required.


The process is shown by the block diagram flowsheet in Figures 6.1 and 6.2.


The dissolution rate of cobalt metal or cobalt oxide is influenced primarily by the oxidation state as well as the surface area of the feed material. An oxidant such as hydrogen peroxide or reductant, such as sugar is added to speed up the digestion. Generally the desirable cobalt concentration of the solution can be reached in less than 8 hours at an elevated temperature (80 to 100 oC). Dissolution difficulties have recently been encountered by some domestic cobalt sulfate producers with Russian cobalt ingots due to the low surface area of the material.

The impurity metals such as iron, aluminum and chromium are usually removed by precipitation at a Ph of 5.

A final adjustment of the solution strength is usually required before storage. This will be accomplished by either evaporation or dilution. There is little risk of crystallization or other product degradation during storage and shipment.

PROCESS FLOWSHEET FOR COBALT SULFATE PRODUCTION






THIS DRAWING IS THE PROPERTY OF
HECLA MINING COMPANY
THIS DRAWING IS FURNISHED FOR THE SOLE USE
OF THE RECIPIENT AND ACCEPTANCE OF THE SAME
CONSTITUTES AN AGREEMENT THAT IT WILL NOT
BE PUBLISHED REPRODUCED OR GIVEN TO ANY
OTHER PARTY WITHOUT OUR PERMISSION UNLESS
FURNISHED TO RECIPIENT UNDER CONTRACT PROVISIONS
AND SHALL REMAIN THE PROPERTY OF HECLA MINING CO.
SUBJECT TO RETURN UPON REQUEST


APEX UNIT

COBALT SULFATE PROJECT

DRAWN BY:	JB BESS
APPROVED BY	BRENT WILLOUGHBY
DATE	
DRAWING NUMBER	



SECTION **A**
6268-L002



SECTION **B**
6268-L002

LEGEND

- EXISTING EQUIPMENT & STRUCTURES
- EXISTING EQUIP. RELOCATED OR REUSED
- NEW EQUIPMENT & STRUCTURES

0601-M002 01/13/94 16:45 JAP

REV	DATE	BY	CHECK	DESCRIPTION OF REVISION	REV	DATE	BY	CHECK	DESCRIPTION OF REVISION




ROBERTS & SCHAEFER
Company
ENGINEERS AND CONTRACTORS
CHICAGO-PITTSBURGH-SALT LAKE CITY R&S JOB #6268

DESIGNED BY J.A. PETERSON
CHECKED BY
APPROVED BY

GENERAL ARRANGEMENT ELEVATIONS
COBALT CARBONITE
HECLA MINING COMPANY
APEX UNIT, ST. GEORGE UT

SCALE 1/8" = 1'-0"
DATE 12/16/93
0601-M002

THIS DRAWING IN DESIGN AND DETAIL IS OUR PROPERTY AND MUST NOT BE USED EXCEPT IN CONNECTION WITH OUR WORK. ALL RIGHTS OF DESIGN OR INVENTION ARE RESERVED.



LEGEND

- EXISTING EQUIPMENT & STRUCTURES
- EXISTING EQUIP. RELOCATED OR REUSED
- NEW EQUIPMENT & STRUCTURES

REV.	DATE	BY	CHECK	DESCRIPTION OF REVISION
1	1/5/94	JAP		ISSUED FOR REPORT
2	12/23/93	JAP		ISSUED FOR REVIEW



ROBERTS & SCHAEFER
ENGINEERS AND CONTRACTORS
CHICAGO-PITTSBURGH-SALT LAKE CITY
R&S JOB #6268

DESIGNED BY J.A. PETERSON
CHECKED BY
APPROVED BY

GENERAL ARRANGEMENT PLAN
COBALT CARBONATE
HECLA MINING COMPANY
APEX UNIT, ST. GEORGE UT

SCALE 1/8" = 1'-0"
DATE 12/15/93
DRAWING NO. 0601-M001